# ARBORICULTURAL REPORT EKORN TREPLEIE AS APPROVED ARBORICULTURAL CONTRACTOR FIRM ESTABLISHED 2013

Date: 05.12.2019

Name/ reference: arbreport025kongensgate Customer details: Oslo House As /Bjørnar Johnsen +47 917 75 878 <u>Bjornar.johnsen@oslohouse.no</u> Address/ Grdsnr: Kongensgate 21, 1530 Moss Lat 59.43569487 Lon 10.66681433

# **Report Overview**

This inspection and report cover the entire tree stock under the curtilage of Kongensgate 21, Moss, paying special attention the to the large Fagus tree located at Easting: 594543, Northing: 6589753. The client, Oslo House AS and Architect, Edit-atelier are concerned about the health of the tree stock and the safe retention of high value trees.

All construction projects undertaken within proximity to trees require careful planning at the design stage with special considerations and specifications made in relation to trees which are worthy of retention or have high amenity value. A qualified Arboricultural consultant is required from early planning stages to project completion in order to protect tree stock and advise all stakeholders as required.

The report is based upon data collected by Douglas Baylin and Thomas Shepherd over two visits on 18<sup>th</sup> November and 3<sup>rd</sup> December 2019. Weather conditions were overcast, intermittent snow showers, wind speeds up to 2m/s with enough visibility to conduct the inspection. The tree assessment involved visual and tactile inspection from ground level, probing for roots and probing the cracks and cavities on the main stem of T1, with the intention of collecting root and crown spread data, identifying distinct defects and other characteristics of all trees within the confines of the boundary.

Evaluation Key					
Condition Size (relevant to species)					
G - Good	S - Small				
F - Fair	M - Medium				
P - Poor	ML – Medium to Large				
D - Dead	L - Large				

Key To Trees
Fagus sylvatica: Bøk
Acer pseudoplatanus: Platan Lønn
Acer platanoides: Lønn
Pyrus communis: Pære tre



# **Evaluation**

				Size			
Tree	Species	Observations	Condition	class	Age	Rating	Recommendations
		Root Zone					
		Generally, the probe can penetrate to 1m showing soll					
		is loose and no hard rock underneath meaning roots					
		Roots discovered:					
		2m from stem 20cm down West					
		5m from stem 70 cm down West					
		1.5m from stem 70 cm down South West bordering the					
		asphalt.					
		1m from stem 45 cm down North East bordering the					
		asphalt.					
		1m from stem 40cm down South East towards asphalt.					
		Extensive probing on upper car park side along the					
		kerb stone finds very few roots within the top 70 cm, it					
		is surmised that the roots are below this and possibly					
		very deep under the asphalt of the car park.					
		It is apparent that the ground level on the Ssouth side					
		has been raised against the tree by approximately 1m,					
		possibly many years ago.					Suitable for retention
		Main stem:					will require careful
		West stem has old wound completely healed over and					considerations during
		sounding partially hollow up to 30cm above and more					the design and
		than this below the previous pruning wound (when					construction phase of
		tested with resonance mallet).					the site and
		Main union at 2 m fundamentally flawed with					monitoring at all
		included bark on two main unions, however probing					intervals which may
		finds no deep cavities, but solid bark and wood (see					impact health.
		Picture 4&5)					Subsequent health
		Han an analta an North aide of North Doot store					and condition surveys
		Upper cavity on North side of North East stem					are required annually
		ago Cavity chamber is approximately 20 cm in					vears after completion
		diameter cavity entrance is 10 cm across decreasing					of the project with a
		(healing over) and cavity is solid below 20 cm deep.					view to extending the
	Fagus	The wall of the cavity is about 10 to 15 cm thick on the					survey to every three
T1	syľvatica	North side.	G	L	150	2	years after that.

				Size			
Tree	Species	Observations	Condition	class	Age	Rating	Recommendations
		Tiny adventitious roots starting to form inside the					
		cavity.					
		Sounding solid when tested with rubber mallet around					
		the cavity. (see Picture 2&3)					
		Northing: 6520750					
		Northing. $0509/53$ MOH of tree at base: 21 Fm (1m accuracy)					
		Diameter at 1m: 112 5cm					
		Height of crown: 17 5m					
		Root Protection Zone (Radius from tree centre					
		on all sides): 13.62m					
		Other trees on the site are Acer family both Sycamore					
		and Norway maple trees are of no particular interest					
		in comparison to the Fagus tree and that is because of					
		poor structure in the Norway maple and because					
		Sycamore is an invasive species, felling and replanting					
		in suitable locations to the benefit of the construction					
	Acer	project is hereby recommended.					
	pseudoplat	There is another smaller tree to the North East side of					
	anus & Acer	11 with poor main stem union and this Sycamore is					
C1	platanoides	also recommended to be relied and replanted.	F & D	м	10	0	Fell and Replant
01	<i>F</i> ······	One more tree of reasonable interest is a Pear tree	rui	111	40	2	
		further to the North has good habitat potential and					
		because this is a long living tree it has the possibility to					
		contribute to the character of the new building project					
		if it is in a suitable location. It des however have a					
		large cavity on the main stem which, while supporting					Retain if tree does not
	Pyrus	wildlife, is quite large and will shorten the trees					conflict with project
T2	communis	lifespan.	G	L	50	1	layout.

# **Conclusion**

T1 has significant environmental value and should be acknowledged as one of the most monumental trees in the city. Care should be taken to ensure the tree is preserved as a large contributor to the local wildlife, as one of the oldest figures in the city, as an object of inspiration and a historic cultural monument.

Important factors to consider during the planning process are:

The future crown and root reach- growing space must be factored into the new development, the tree will continue to spread out and will need space to grow into.

The root zone and immediate topography- the altering of terrain levels can expose or compact roots, killing them and having a negative effect on the branches and crown, possibly even killing the tree or making it structurally unstable.

Shade on the tree canopy and root zone- the effects of new buildings on the amount of direct sunshine and shade should be considered, reflected sunshine and heat can dry out branches and the rootzone, causing necrosis. A shaded root zone could get waterlogged and prevent insects from aerating the soil, causing roots to suffocate. Shaded branches will die back and become a hazard to those below and adaptive growth could even cause structural failure, if, it increases weight and wind sail and in weak area of the crown.

The effect of the new buildings on the prevailing wind- the effects of 'wind tunnelling' from new buildings on the crown can dry out branches or sections of the crown and the root zone, while also posing a physical threat of fracturing branches through torsional strain.

It is important to understand that dramatic changes can cause disruption to the trees current equilibrium and ruining the tree would be great loss to the property and the future complex.

#### **Recommendations**

- Tree protection zone- this is a physical barrier set up to prevent construction related activity in the trees immediate proximity, in this case for T1 we recommend a circular work zone with a radius of 13.62m. This should be made of solid builders fencing and labelled with 'No Entry' signs.
- 2. If work needs to be carried out within this protection zone, it should be approved or accompanied by a qualified arborist.
- 3. Low branches which hang outside the protection zone should be protected from impact with packing and can also be marked with high visibility tape which will hang down and make workers more aware of the overhanging branches.
- 4. Chemicals and harmful substances should not be used/mixed/delivered near or upwind of the protection zone.
- 5. If any roots of 30mm diameter or larger are exposed, an arborist should be contacted, and the roots subsequently repair pruned. Remedial branch pruning may be necessary after root removal.
- 6. Filling excavated areas and the area surrounding the protection zone should be done with correct soil to encourage root recovery and growth.

#### **Summary**

All stakeholders should review the findings of this report and undertake works as recommended. We look forward to contributing to this project and helping to create a fantastic environment for the new complex.

#### **Validation**

This report is valid for 3 years and should be kept as a record for future inspections to better help evaluation of characteristics and defects.

# **Standard**

All Arboricultural work to be carried out according to industry standard best practice recommendations NS3420 del ZK.

#### **Disclaimer**

Trees are classed as optimum lightweight structures and are immobile, therefore they are forever at the mercy of outside influences such as extreme weather, climatic changes, physical impediment, chemical imbalance and viral vulnerability. Due to the natural growth habit of different tree species and the outside influences on them, no guarantee of tree safety can be given. This report is not a guarantee of tree safety or by any means an absolution of responsibility from the owner. Trees, landscape and any subsequent work or action taken remain the duty and responsibility of the owner. This report is based on the qualifications and experience of the Arboriculturalist who carried out the evaluation.

#### **Declaration:**

Sign	DAB	Date	05/12/2010	
Digii.		Date.	03/12/2019	

# Douglas Mark Baylin, C&G/NPTC/ETW/ISA

Ekorn Trepleie AS, org: 911640562 mva Teigen 30, 1407 Vinterbro www.ekorntrepleie.com douglas@ekorntrepleie.com 40553333/92455185



Picture 1 – Fagus sylvatica (T1)



Picture 2&3 – Excavation of leaves and humus from scaffold limb to aid inspection of open cavity.



Picture 4&5 – Main union with inclusion of bark/cambium layer causing an inherent weakness, however no deep cavities or excessive decay was noted on inspection



Picture 6 – Positioning of T1 showing crown reach (purple) and root protection zone(red). Any work inside the root protection zone should be accompanied by an arborist.